

Katalyst-Light® Filter Installation in Accra, Ghana



Katalyst-Light® Filter Installation in Accra, Ghana



Raw water



Filtered water

Katalyst-Light® Filter Installation in Accra, Ghana



Comment from the Customer:

The installation of the katalox light was done yesterday and tested. I share attached pictures. Water samples are as below , both before and after. The problem about this particular ground (bore hole) water, located on a domestic premises is iron contaminants. Results are so exciting though as could be seen in the pictures .

-Owusu Darko, Isaac

Dated: 15 August 2014